

Question	Answer	Comment to Answer
BOX Serial Number (it is the kapton label on both sides of the chassis)	"FEB8017"	
Address Rotary Switch (Station,Quarter-Layer,Module e.g. 335 -> Station 3, Q3, L0, M5)	349	
Position it occupied in OT (e.g. C-Frame T3-Q13-XU, L0, Q3, M5, should match address)	T3-Q02-XU Q0-L1-M9	
Connector/Pins problems (i.e. broken pins or connectors, etc.)		
SPECS Communication (i.e. box accepted commands, etc.)		
PERFORMANCE IN TSTPLS RUN (i.e. TSTPLS events received, TSTPLS timing ok, etc.)		
BX/EVT COUNTERS MISMATCH (i.e. errors reported by the TELL1 concerning BX or EVTID, etc.)	Mainly BxID and L0Id errors in data, but also "GOL not equal", "OTIS HDR" Multiple resets did not help.	
BIT ERROR TEST (was a GOL bit error test performed and was it ok)		
DATA TRANSMISSION (i.e. was data received in EVB, anything strange etc.)	Tell1 PVSS panel showed error for this link. Errors in data, 3-SEP-2016: https://lblogbook.cern.ch/OT/4725	
HV (e.g. HV trips, or all ok, but don't see particles, etc.)		
Operational Description (e.g. checked swapping cables or box, or whatever other study you did)		
Other Remarks	Suspect broken GOL or OTIS. Took off the detector on 15/09/2016 https://lblogbook.cern.ch/OT/4758	