

Sample	Rack	Position	Side	Line	Label	Installed by	Status	Results Hydrocarbonats
1	Distribution rack		A	Exhaust	204(35)OT	Cegelec	not commissioned	Traces
2	Distribution rack		A	Mixture in	202(28)OT	Cegelec	not commissioned	Negligible Traces
3	Distribution rack		C	Mixture in	201OT-CRLP249	Cegelec	commissioned	Negligible Traces
4	Pre-Distributionrack, A3B04		A	Exhaust	204-OT	Cryotec	not commissioned	Non negligible Traces
5	Pre-Distributionrack, A3B04		C	Exhaust	203OT-CRLP250	Cryotec	commissioned	Pollutions
6	Pre-Distributionrack, A3B05		C	Mixture in	201OT-CRLP249	Cryotec	commissioned	Pollutions
7			C	O-ring on sample 6		Cryotec	commissioned	Pollutions
8	Pre-Distributionrack, A3B05		A	Mixture in	202	Cryotec	commissioned	Non negligible Traces
9		Close to Gantry	A	Mixture in		Cegelec	not commissioned	Non negligible Traces
10		Close to Gantry	A	Exhaust		Cegelec	not commissioned	Non negligible Traces
11		Wall	A	Mixture in	202	Cryotec	not commissioned	Traces
12		Wall	A	Exhaust	204	Cryotec	not commissioned	Traces

For all samples no Silicon has been found.