
2a01.txt
2a02.txt
2a03.txt
2a04.txt
track resistance [mV drop for 4 mA]
meas. point
0.035
0.03
0.025
0.02
0.015
0.01
0.005
0
0
10
20
30
40
50


2a05.txt
2a06.txt
2a07.txt
2a08.txt
track resistance [mV drop for 4 mA]
meas. point


2a09.txt
2a10.txt
2a11.txt
2a12.txt
track resistance [mV drop for 4 mA]
meas. point


2a13.txt
2a14.txt
2a15.txt
2a16.txt
track resistance [mV drop for 4 mA]
meas. point
0.035
0.03
0.025
0.02
0.015
0.01
0.005
0
0
10
20
30
40
50


2a17.txt
2a18.txt
2a19.txt
2a20.txt
track resistance [mV drop for 4 mA]
meas. point
0.035
0.03
0.025
0.02
0.015
0.01
0.005
0
0
10
20
30
40
50


2a21.txt
2a22.txt
2a23.txt
2a24.txt
track resistance [mV drop for 4 mA]
meas. point


2a25.txt
2a26.txt
2a27a.txt
2a27b.txt
track resistance [mV drop for 4 mA]
meas. point


2a27.txt
2a28.txt
2a29a.txt
2a29b.txt
track resistance [mV drop for 4 mA]
meas. point


2a29.txt
2a51.txt
2a52.txt
2a53.txt
track resistance [mV drop for 4 mA]
meas. point


2a54.txt
2a55.txt
2a56.txt
2a57.txt
track resistance [mV drop for 4 mA]
meas. point


2a58.txt
2a59.txt
2a60.txt
2a61.txt
track resistance [mV drop for 4 mA]
meas. point
0
0.005
0.01
0.015
0.02
0.025
0.03
0.035
0
10
20
30
40
50


2a62.txt
2a63.txt
2a64.txt
2a65.txt
track resistance [mV drop for 4 mA]
meas. point


2a66.txt
2a67.txt
2a68.txt
2a69.txt
track resistance [mV drop for 4 mA]
meas. point


2a70.txt
2a71.txt
2a72.txt
2a73.txt
track resistance [mV drop for 4 mA]
meas. point


2a74.txt
2a75.txt
2a76.txt
2a77.txt
track resistance [mV drop for 4 mA]
meas. point


2a78.txt
2a80.txt
2b01.txt
2b02.txt
track resistance [mV drop for 4 mA]
meas. point


2b03.txt
2b04.txt
2b05.txt
2b06.txt
track resistance [mV drop for 4 mA]
meas. point


2b07.txt
2b08.txt
2b09.txt
2b10.txt
track resistance [mV drop for 4 mA]
meas. point


2b11.txt
2b12.txt
2b13.txt
2b14.txt
track resistance [mV drop for 4 mA]
meas. point


2b15.txt
2b16.txt
2b17.txt
2b18.txt
track resistance [mV drop for 4 mA]
meas. point


2b19.txt
2b20.txt
2b21.txt
2b22.txt
track resistance [mV drop for 4 mA]
meas. point


2b23.txt
2b24.txt
2b25.txt
2b26.txt
track resistance [mV drop for 4 mA]
meas. point


2b27.txt
2b28.txt
2b29.txt
2b51.txt
track resistance [mV drop for 4 mA]
meas. point


2b52.txt
2b53.txt
2b54.txt
2b55.txt
track resistance [mV drop for 4 mA]
meas. point


2b56.txt
2b57.txt
2b58.txt
2b59.txt
track resistance [mV drop for 4 mA]
meas. point


2b60.txt
2b61.txt
2b62.txt
2b63.txt
track resistance [mV drop for 4 mA]
meas. point
0
0.005
0.01
0.015
0.02
0.025
0.03
0.035
0
10
20
30
40
50


2b64.txt
2b65.txt
2b66.txt
2b67.txt
track resistance [mV drop for 4 mA]
meas. point


2b68.txt
2b69.txt
2b70.txt
2b71.txt
track resistance [mV drop for 4 mA]
meas. point


2b72.txt
2b73.txt
2b74.txt
2b75.txt
track resistance [mV drop for 4 mA]
meas. point


2b76.txt
2b77.txt
2b78.txt
2b79.txt
track resistance [mV drop for 4 mA]
meas. point


2b80.txt
2b81.txt
p2a01.txt
p2a02.txt
track resistance [mV drop for 4 mA]
meas. point


p2a03.txt
p2a04.txt
p2a05.txt
p2a06.txt
track resistance [mV drop for 4 mA]
meas. point


p2a07.txt
p2a08.txt
p2b01.txt
p2b02.txt
track resistance [mV drop for 4 mA]
meas. point
0.035
0.03
0.025
0.02
0.015
0.01
0.005
0
0
10
20
30
40
50


p2b03.txt
p2b04.txt
p2b05.txt
p2b06.txt
track resistance [mV drop for 4 mA]
meas. point
0.035
0.03
0.025
0.02
0.015
0.01
0.005
0
0
10
20
30
40
50


p2b07.txt
track resistance [mV drop for 4 mA]
meas. point


p2b08.txt
track resistance [mV drop for 4 mA]
meas. point


p2b07.txt
track resistance [mV drop for 4 mA]
meas. point


p2b08.txt
track resistance [mV drop for 4 mA]
meas. point


p2b07.txt
track resistance [mV drop for 4 mA]
meas. point


p2b08.txt
track resistance [mV drop for 4 mA]
meas. point


p2b07.txt
track resistance [mV drop for 4 mA]
meas. point


p2b08.txt
track resistance [mV drop for 4 mA]
meas. point