

Status of the ODIN S-Link Cards

Type	Serial No	Location	Date	
LSC	2001	On CSMux #3	21-okt-03	
LDC	2002	In stock	4-aug-04	
LSC	2003	On CSMux #1	5-nov-03	
LDC	2004	In stock	4-aug-04	
LSC	2005	On CSMux #2	21-okt-03	
LDC	2006	In stock	4-aug-04	
LSC	2007	"Argos" MROD-Out 6	2-jul-03	
LDC	2008	In stock	4-aug-04	
LSC	2009	H8 Testbeam	9-aug-03	
LDC	2010	In stock (Made 5 Volt!)	27-okt-03	
LSC	2011	ShaSLINK in PC "Trippel" ???	5-dec-03	
LDC	2012	In stock	4-aug-04	
LSC	2013	"Fuji" MROD-out 6	1-okt-03	
LDC	2014	H8 Testbeam	9-aug-04	
LSC	2015	H8 Testbeam	2-jul-03	
LDC	2016	In stock	4-nov-03	During transmission from LSC 2013 the "Err" led lit up. Also tried the output of LSC 2013 on other LDCs but these seem to be okay so this looks as a problem on the LDC 2016. After moving LDC 2016 to "Fuji" MROD-in 9E-A the problem did no longer occur. Try to put it back to MROD-in 9C-A...