
TCK,TMS, TDI Measured at Slot 3; TDO Measured at Slot 21 Series termination TCK = 0 (6MHz)



PJ, 28 Nov 2006

TCK,TMS, TDI Measured at Slot 3; TDO Measured at Slot 21 Series termination TCK = 0 (3MHz)



PJ, 28 Nov 2006